



101- 104

									*	
			1	2	L	C				
101-1	1.400-15. 1.110	1	100	60	20	300	-	-	0,6	70 .
-3	-01					200	-	-	0,5	60 .
-6	-02					80	40	8	0,6	70 .
102-1	-03		150	90	30	300	-	-	0,7	80 .
-3	-04					200	-	-	0,6	70 .
-6	-05					80	40	8	0,7	80 .
103-1	-06		200	120	40	300	-	-	0,9	100 .
-3	-07					200	-	-	0,8	90 .
-6	-08					80	40	8	0,9	100 .
104-1	-09	2	-	-	300	-	-	3,4	280 .	
-3	-10				200	-	-	3,2	260 .	
-6	-11				80	40	8	3,5	270 .	

* -